

Assessment of Dam Safety of Coal Combustion Surface Impoundments

Indianapolis Power & Light Company

Harding Street Generating Station

3700 South Harding Street

Indianapolis, Indiana

Prepared for:

U. S. Environmental Protection Agency

Washington, D. C.

November 15, 2010

CDM Project No.: 76658.1801.034. SIT.HRDNG

Preface

The assessment of the general condition of the impoundments is based upon available data and visual observations. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of this report.

In reviewing this report, it should be realized that the reported condition of the impoundments is based on observations of field conditions at the time of assessment, along with data made available to the assessment team. In cases where an impoundment may have been lowered or drained prior to the assessment, such action, while improving the stability and safety of the impoundment, removes the normal load on the structure and may obscure certain conditions, which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is critical to note that the condition of the impoundments depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the impoundment at the time of the assessment is representative of the condition of the impoundment at some point in the future. Only through continued care and assessment can there be any chance that unsafe conditions will be detected.

Prepared By:

CDM

I certify that the management unit (s) referenced herein have been assessed on April 29 and 30, 2010:



Michael L. Schumaker, P.E.
Senior Geotechnical Engineer
PE10708838



W. J. Friers, P.E.
Senior Civil Engineer



Kyle R. King, E.I.T.
Geotechnical Engineer

CDM

Contents

Section 1	Introduction and Project Description	
1.1	Introduction.....	1-1
1.2	State Regulation	1-1
	1.2.1 Permits	1-1
1.3	Datum.....	1-1
1.4	Site Description and Location.....	1-2
	1.4.1 CCW Impoundment Construction and Historical Information.....	1-2
	1.4.2 Current CCW Impoundmnet Configuration.....	1-3
	1.4.3 Other Impoundments	1-5
1.5	Previously Identified Safety Issues	1-5
1.6	Site Geology.....	1-5
Section 2	Field Assessment	
2.1	Visual Observations	2-1
2.2	Ash Pond 1.....	2-2
	2.2.1 Exterior Slope	2-2
	2.2.2 Crest.....	2-2
	2.2.3 Interior Slope	2-2
	2.2.4 Outlet Pipe	2-3
2.3	Ash Pond 2.....	2-3
	2.3.1 Exterior Slope	2-3
	2.3.2 Crest.....	2-4
	2.3.3 Interior Slope	2-4
	2.3.4 Outlet Pipes	2-4
2.4	Ash Pond 2A	2-4
	2.4.1 Exterior Slope	2-4
	2.4.2 Crest.....	2-5
	2.4.3 Interior Slope	2-5
	2.4.4 Outlet Pipes	2-5
2.5	Ash Pond 2B	2-6
	2.5.1 Exterior Slope	2-6
	2.5.2 Crest.....	2-6
	2.5.3 Interior Slope	2-6
	2.5.4 Outlet Structure	2-6
2.6	Ash Pond 3.....	2-7
	2.6.1 Exterior Slope	2-7
	2.6.2 Crest.....	2-7
	2.6.3 Interior Slope	2-7
	2.6.4 Outlet Structure	2-8
2.7	Ash Pond 4.....	2-8
	2.7.1 Exterior Slope	2-8

	2.7.2 Crest.....	2-8
	2.7.3 Interior Slope	2-9
	2.7.4 Outlet Pipes	2-9
2.8	Ash Pond 4A	2-9
	2.8.1 Exterior Slope	2-9
	2.8.2 Crest.....	2-10
	2.8.3 Interior Slope	2-10
	2.8.4 Outlet Pipes	2-10
2.9	Ash Pond 4B	2-10
	2.9.1 Exterior Slope	2-10
	2.9.2 Crest.....	2-11
	2.9.3 Interior Slope	2-11
	2.9.4 Outlet Pipes	2-11
2.10	Monitoring Instrumentation	2-11
Section 3	Data Evaluation	
3.1	Design Assumptions	3-1
3.2	Hydrologic and Hydraulic Design.....	3-1
3.3	Structural Adequacy and Stability	3-1
	3.3.1 Ash Pond Impoundments	3-1
3.4	Foundation Conditions.....	3-2
3.5	Operations and Maintenance.....	3-2
Section 4	Conclusions and Recommendations	
4.1	Hazard Classification.....	4-1
4.2	Acknowledgement of CCW Impoundment Unit Condition.....	4-1
4.3	Maintaining and Controlling Vegetation Growth	4-1
4.4	Erosion Protection and Repair	4-3
4.5	Animal Control	4-4
4.6	Instrumentation	4-4
4.7	Impoundment Hydraulic and Stability Analysis.....	4-5
4.8	Inspection Recommendations.....	4-5
4.9	Emergency Action Plan	4-6
Section 5	Closing	
Section 6	Reports and References	
Appendices		
	<i>Appendix A – USEPA Coal Combustion Dam Inspection Checklist Forms</i>	
	<i>Appendix B – Photographs</i>	
	<i>Appendix C – Photo GPS Locations</i>	

Tables

Table 1	Approximate Ash Pond Low Crest Elevations and Areas	1-4
Table 2	Approximate Precipitation Prior to Site Visit.....	2-1
Table 3	Minimum Required Factors of Safety	3-2
Table 4	Recommended Impoundment Hazard Classification Ratings	4-2

Figures

Figure 1	Locus Plan
Figure 2	Critical Infrastructure Plan
Figure 3	Aerial Map
Figure 4	1996 Survey Map
Figure 5	Ash Pond 2 Final Levee Improvements
Figure 6	Ash Pond Details
Figure 7	Ash Ponds 3 and 4 Plan View
Figure 8a	Patriot Engineering Boring Location Plan
Figure 8b	Patriot Engineering Boring Log
Figure 9a	Ash Pond 1 Photograph Location Plan
Figure 9b	Ash Pond 2 Photograph Location Plan
Figure 9c	Ash Pond 2A Photograph Location Plan
Figure 9d	Ash Pond 2B Photograph Location Plan
Figure 9e	Ash Pond 3 Photograph Location Plan
Figure 9f	Ash Pond 4 Photograph Location Plan
Figure 9g	Ash Pond 4A Photograph Location Plan
Figure 9h	Ash Pond 4B Photograph Location Plan
Figure 10	Typical Bi-weekly Inspection Checklist

Section 1

Introduction and Project Description

1.1 Introduction

CDM was contracted by the United States Environmental Protection Agency (USEPA) to perform site assessments of selected coal combustion waste (CCW) surface impoundments. As part of this contract, CDM performed a site assessment at the Harding Street (HS) Generating Station, owned by Indianapolis Power & Light Company (IPL).

CDM made a site visit to the HS Generating Station on April 28 and 29, 2010 to collect relevant information, inventory the impoundments, and perform visual assessments of the impoundments.

CDM representatives William Friers, P.E. and Kyle R. King were accompanied by the following individuals:

<u>Company</u>	<u>Name and Title</u>
IPL	Nysa L. Hogue, Senior Environmental Coordinator (Ash Pond 1)
IPL	Gary Finchum, Plant Leader (Ash Pond 2 and 4)
IPL	Thomas O'Leary, Environmental Coordinator (All Ash Ponds)

1.2 State Regulation

The Indiana Department of Natural Resources (IDNR) Water Division is responsible for the State's dam safety program. It is our understanding that to date IDNR has not been actively involved in the regulation of CCW impoundments. IPL staff stated there are no State inspection reports for the impoundments at the HS Generating Station.

1.2.1 Permits

The IPL HS Generating Station was issued a permit under the National Pollutant Discharge Elimination System (NPDES) authorizing discharge to the White River in accordance with effluent limitations, monitoring requirements, and other conditions set forth in the permit. The station's current permit will expire September 30, 2011. The permit number is IN0004685.

1.3 Datum

Elevations are referenced to the National Geodetic Vertical Datum of 1929 (NGVD 29). Directional coordinates are referenced to magnetic north. IPL's Harding Street plant datum is 2.1-feet lower than NCVD 29.

1.4 Site Description and Location

The HS Generating Station is located on the southwest side of Indianapolis, Marion County, Indiana as shown on [Figure 1](#). The state boundary with Illinois and Michigan is approximately 70 miles west and 145 miles north of the site, respectively. The HS Generating Station is located within the city limits of Indianapolis. The area around the HS Generating Station showing critical infrastructure within approximately five miles down gradient of the impoundments is shown on [Figure 2](#). The nearest residential area which is located approximately 1.5 miles downstream (southwest) from the site is also shown in Figure 2. An aerial view of the Ash Pond Impoundments is shown on [Figure 3](#).

1.4.1 CCW Impoundment Construction and Historical Information

The HS Generating Station began operation in September 1941. The CCW is generated by Unit 5 (on line since 1958), Unit 6 (on-line since 1961) and Unit 7 (on-line since 1973).

Based on a survey map dated 1996 (shown on [Figure 4](#)) and previous reports, the embankment crests for the ponds ranged from El. 682 (Ash Pond 4) to El. 720 (Ash Pond 2).

Ash Pond 1 is the original CCW impoundment at HS and was commissioned in 1958. In 1995 the crest elevation of the embankment was raised to approximately El. 686. In 1998 the crest was widened to approximately 25 feet to accommodate truck hauling and other vehicle traffic. The interior and exterior slopes of the embankment were constructed at approximately 3H:1V.

Ash Pond 2 was commissioned in 1968. Based on information contained in IPL project files, a "Wing levee" was constructed in 1980 within Ash Pond 2. In 1992 the "Perry K ash disposal facility" was also constructed within Ash Pond 2. Remnants of several interior embankments were observed at the time of the assessment, however neither the "Wing levee" nor the "Perry K ash disposal facility" were evident. IPL drawing titled "Pond 2 Levee Improvements Ash Pond Area Plan", dated October 27, 2004, called for the removal of several embankments within Ash Pond 2 (shown on [Figure 5](#)).

As reported in IPL's letter of March 26, 2009 from William Marsan to the USEPA, Ash Pond 2 embankments crests were raised in 1995 to El. 686. In 2001 they were again raised approximately 17 feet. In 2006 they were raised a final time approximately 20 feet to approximately El. 720. The embankment interior and exterior slopes are approximately 3H:1V and are constructed of compacted ash materials with approximately 6 inches of shale armor. As the embankment was raised, a 5-foot-thick geosynthetic clay/clay core was placed along the interior of the pond. The geosynthetic clay/clay core (liner) extends from the top of the embankment to

undisturbed soil at the base of the embankment, and then extends horizontally toward the toe of the exterior slope, as shown on [Figure 6](#), Section B-B. The information shown on Section B-B appears to indicate that the expanded embankment may have been constructed over hydraulically placed ash materials previously placed in the pond.

Ash Ponds 2A, 2B and 2C were commissioned in approximately 1992. At some point after the 1992 commissioning, the divider embankment that formed the east side of Ash Pond 2C was removed, combining Ash Ponds 2A and 2C and creating a single larger pond named Ash Pond 2A. Information regarding the dimensions of the original embankment construction is not available.

Ash Pond 3 was commissioned in approximately 1977 with modifications and vertical expansions in 1995 to El. 686. In 1998 the embankment crest was widened to approximately 40 feet to accommodate truck traffic. The interior and exterior slopes of the embankment were constructed at approximately 3H:1V.

Ash Pond 4 was gravel borrow pit prior to 1983. Ash Pond 4 was commissioned in approximately 1983. Modifications and vertical expansions occurred in 1995 raising the crest to approximately El. 686 and horizontal expansions to accommodate truck traffic were made in 1998 (as shown on [Figure 7](#)). At some time after commissioning, divider embankments were constructed within the original footprint of Ash Pond 4 to create Ash Ponds 4A and 4B.

1.4.2 Current CCW Impoundment Configuration

The impoundments at the HS Generating Station currently are used as settling ponds for CCW waste and other plant wastes. CCW sluiced into the impoundments include:

- Bottom ash;
- Fly ash;
- Boiler slag;
- Ash and pyrite system;
- Flue gas emission control residuals;
- Boiler blowdown; and
- Boiler, condenser, air pre-heater, and cooling cleaning wastes.

Other plant wastes sluiced into the ash ponds include liquids from:

- Recirculating cooling tower blowdown;
- Demineralizer wastes;
- Flue gas desulfurization (FGD) system blowdown;
- Miscellaneous FGD wastes;
- Floor drains;

- Stormwater runoff;
- Water treatment wastes;
- Metal cleaning wastes;;
- River dredging materials; and
- Condensate polisher waste.

There are currently eight CCW Units at the HS Generating Station as shown on Figure 3. They include: Ash Pond 1, Ash Pond 2, Ash Pond 2A, Ash Pond 2B, Ash Pond 3, Ash Pond 4, Ash Pond 4A, and Ash Pond 4B. The approximate lowest crest elevations of the embankments and pond areas are shown on [Table 1](#).

Table 1 – Approximate Ash Pond Low Crest Elevations and Areas

Ash Pond Number	Approximate Lowest Crest Elevation (NGVD, feet)	Approximate Ash Pond Area (Acres)
1	685	7
2	720	30
2A	684	3
2B	684	2
3	685	9.5
4	682	21
4A	685	1
4B	684	5

Ash Pond 1 is currently inactive and dry. When in operation, water levels in Ash Pond 1 and Ash Pond 2A are balanced through a 30-inch-diameter Corrugated Metal Pipe (CMP). The invert of the pipe is approximately El. 681.5.

Ash Pond 2 does not have an inlet structure. Historically, IPL has pumped CCW into this pond using a hydraulic dredge. Water contained in the dredge material evaporates and infiltrates the dredge spoils over time. In the event that water levels within the pond reach El. 695 or higher, water will be discharged through an overflow structure, located at the east end of the pond. The 30-inch-diameter CMP overflow structure, with an invert at approximately El. 695, discharges into Pond 2A at approximate invert El. 684.6.

Material is sluiced into Ash Pond 2A from four (4) pipelines, consisting of two sump pit lines, the cinder pit line, and the FGD hydroclone line. Water flows from Ash Pond 2A into Ash Pond 2B through a 30-inch-diameter CMP outlet pipe, with an approximate invert elevation of El. 680.5. Water also flows from Ash Pond 2A into

Ash Pond 1 through a 30-inch-diameter CMP, with an approximate invert elevation of El. 681.5.

Ash Pond 2B is used as a secondary pond for settling of finer material. Water flows from Ash Pond 2B into Ash Pond 4A and is controlled by a 30-inch isolation valve, with a centerline at El. 680.8. The discharge pipe is a 30-inch-diameter CMP with an invert elevation of El. 682.

Ash Pond 3 is the final settling pond before water is discharged into Lick Creek. Flow into Ash Pond 3 comes directly from Ash Pond 4B, through a 30-inch-diameter CMP. The invert from Ash Pond 4B has an invert of approximately El. 681.5. Water from Ash Pond 3 flows through three 12-inch-diameter welded steel pipes, with invert elevations of approximately El. 678.5, to a drop outlet structure, and then into Lick Creek via an 18-inch-diameter reinforced concrete pipe.

Material is sluiced into Ash Pond 4 by a 9-inch-diameter and a 12-inch diameter pipeline and is used as a primary settling pond. Water from Ash Pond 4 discharges into Ash Pond 4B through two (2) 30-inch-diameter CMPs, that have an invert elevation of approximately El. 681.0.

Fly ash and bottom ash contained in Ash Pond 4A are currently being processed. Ash Pond 4B is being used for the settlement of fines. Water levels in Ash Pond 4B and Ash Pond 4A are balanced with a 30-inch-diameter CMP equalizer pipe that extends between the two ponds. Ash Pond 4A is charged by two (2) FGD sump lines.

The outlet from Ash Pond 4BA to Ash Pond 3 is through a 30-inch-diameter CMP, with an invert elevation of approximately El. 681.5.

1.4.3 Other Impoundments

No other impoundments were identified at the HS Generating Station.

1.5 Previously Identified Safety Issues

Based on our review of the information provided to CDM by plant personnel and the USEPA, there have been no identified safety issues at the Ash Pond Complex in the last 10 years.

1.6 Site Geology

The Ash Pond Complex is located east of the White River adjacent to the floodplain. The ground surface elevation at the toe of the impoundments is approximately El. 670. According to the Geologic Map of Indiana, bedrock is likely comprised of siltstone, shale, sandstone, and minor amounts of limestone as part of the Borden

Group. The available data indicate that bedrock is anticipated to exist approximately 50 to 80 feet below existing site grades. Based the information reviewed, glacial till overlies bedrock and consists of an unsorted mixture of sand, silt, clay and boulders that was deposited as glaciers advanced into Indiana.

Based on a boring advanced in 2006 by Patriot Engineering, existing soils present in the vicinity of the impoundment systems consist of silty clays and sand with varying amounts of gravel. The boring location plan is shown on [Figure 8a](#) and the boring log is shown on [Figure 8b](#).

Section 2

Field Assessment

2.1 Visual Observations

CDM performed a visual assessment of the CCW impoundments at the HS Generating Station. The perimeter and divider embankments of the impoundments total approximately 17,210 feet in length and are up to 48 feet high. The assessments were completed following the general procedures and considerations contained in Federal Emergency Management Agency's (FEMA's) Federal Guidelines for Dam Safety (April 2004) to make observations concerning settlement, movement, erosion, seepage, leakage, cracking, and deterioration. A Coal Combustion Dam Inspection Checklist and CCW Impoundment Inspection Form, developed by USEPA, were completed on site for each impoundment during the site visit. Copies of these forms are included in **Appendix A**. Photograph Location Plans are shown in **Figures 9a through 9h**, and photographs are included in **Appendix B**. Photograph locations were logged using a GPS device. The photograph coordinates are listed in **Appendix C**.

CDM visited the site on April 29, 2010 and April 30, 2010 to make visual assessments of the impoundments. The weather was generally sunny and windy with daytime high temperatures between 44 and 79 degrees Fahrenheit. The daily total precipitation prior to the site visit is shown in **Table 2**. The data were recorded at the Indianapolis Airport which is approximately five miles west of the HS Generating Station.

Table 2 – Approximate Precipitation Prior to Site Visit

Dates of Site Visits - April 29, 2010 & April 30, 2010		
Day	Date	Precipitation (inches)
Thursday	April 22	0.00
Friday	April 23	0.05
Saturday	April 24	0.23
Sunday	April 25	0.87
Monday	April 26	0.00
Tuesday	April 27	0.00
Wednesday	April 28	0.00
Thursday	April 29	0.00
Friday	April 30	0.00
Total	Week Prior to Site Visit	1.15
Total	Month Prior to Site Visit	2.97

2.2 Ash Pond 1

An overview of Ash Pond 1 photograph locations is shown on Figure 9a. Ash Pond 1 was inactive and dry at the time of the assessment. The pond's west, south and east embankments serve as divider embankments with Ash Ponds 2, 2A and 3, respectively. Based on information provided by IPL, Ash Pond 1 was commissioned in 1958.

2.2.1 Exterior Slope

The exterior slopes appear to be in fair condition. The exterior slope of the north embankment is, for the most part, heavily covered with trees up to 18 inches in diameter and brush (Photograph 14). Although vegetation nearly obscured observations on the north embankment, it appeared that the exterior slope of the north embankment was approximately 3H:1V. Dense vegetation precluded observation of any erosion or rodent burrows on the north embankment (Photograph 14).

The south, east and west embankments were covered with medium dense vegetation ranging from approximately 18 to 48 inches in height. The exterior slopes on the west, south and east embankments ranged from approximately 2.5H:1V to 3H:1V. Riprap, with an underlying geotextile has been placed on sections of the east and south embankments, apparently for erosion protection (Photographs 46, 47, and 79). Surface erosion was observed along portions of the south embankment. An erosion rill on the south embankment had undercut plant sluice lines by as much as 14 inches across a distance of approximately 10 feet (Photographs 48 and 49). The east embankment had areas of erosion, including sections with apparent surficial slope failures and undermining (Photographs 78, 81 and 82).

2.2.2 Crest

The crest of Ash Pond 1 appeared to be in satisfactory condition (Photographs 1, 8, 11, and 12). The crest was approximately 15 feet wide with the exception of the haul road portion of the crest on the north embankment that was approximately 20 feet wide. The entire crest is exposed to vehicle traffic. Depressions and minor ruts, apparently due to vehicle traffic, were observed on the crest of each embankment (Photograph 1, 8 and 12). The crest surface appears to consist of compacted granular soils. A section of the crest of the south embankment has been excavated and remains open, apparently to facilitate the repair of a joint on the cinder pit sluice line (Photograph 5).

2.2.3 Interior Slope

The interior slopes appear to be in fair condition. Light vegetation covers the south and east embankments (Photographs 4 and 9). The interior slopes are approximately 3H:1V. No armoring of the interior slope is present, and much of the pond's interior surface consists of exposed ash. Areas of beaching and erosion were observed on portions of the unprotected slope surface (Photograph 16). Beaching is defined as the progressive erosion of the interior embankment slope caused by repeated wave action

striking the embankment just above the water line, displacing material from the face of the slope and depositing it at a point farther down the slope as the wave recedes, creating a beach. Scarification resulting from equipment tracks was present along the west embankment (Photograph 19).

2.2.4 Outlet Pipe

The outlet pipe in Ash Pond 1 appears to be in good condition. A 30-inch-diameter CMP tee is located at the southwestern end of the pond, connecting the pond with Ash Pond 2A (Photograph 2). No unusual movement was observed around the pipe penetration.

2.3 Ash Pond 2

An overview of Ash Pond 2 photograph locations is shown on Figure 9b. Ash Pond 2 was inactive and dry at the time of the assessment. Water generally leaves the pond through evaporation and infiltration. Based on information provided by IPL, Ash Pond 2 was commissioned in 1968.

2.3.1 Exterior Slope

The exterior slopes of the impoundment are approximately 3H:1V. The slopes appear to be in fair condition. The south embankment slope is generally covered with weathered shale fill. Numerous erosion rills were present on the exterior slope of the south embankment (Photographs 25, 27, 29, and 32). Vegetation including brush and saplings (up to 3 inches in diameter) were observed along the toe of the south embankment (Photos 22 and 23). Riprap has been placed over a geotextile in 3 locations on the south embankment (Photos 28 and 29). The riprap appears to be remediation efforts in the vicinity of erosion rills, previously documented in BT SQUARED, Inc. (BT SQUARED) and Geosyntec's September 2008 inspection report.

The surface of the west embankment slope is covered with grass and weeds ranging from 6 to 12 inches in height (Photograph 37).

Areas of minor surface erosion were observed on the north embankment exterior slope. An area of the slope face has riprap on the surface placed from the edge of the crest to a point approximately 30 feet above the toe of the slope (Photographs 38 and 39). The north embankment exterior slope has light grass cover. The toe of the slope has heavy vegetation including trees (up to 24 inches in diameter) (Photograph 40).

Riprap has been placed over approximately 50 percent of the east embankment exterior slope (generally on the north part of the embankment). Vegetation on the remaining embankment was sparse and generally 10 to 18 inches high (Photograph 45).

2.3.2 Crest

The crest appears to be in satisfactory condition (Photographs 24 and 40). The average crest width is approximately 25 feet. The entire crest is subjected to vehicle traffic. Depressions and ruts approximately 12 inches deep, apparently due to vehicle traffic, were observed on the crest of the south embankment (Photograph 24).

2.3.3 Interior Slope

The interior slopes appear to be in generally poor condition. The interior slopes are approximately 3H:1V. No armoring of the interior slope is present and much of the pond's interior surface consists of exposed ash. There are deep erosion rills and significant surface sloughs on approximately 40 percent of the south embankment interior slope (Photographs 26, 33, 34 and 35).

Dredge fill material has been deposited in the west end of the impoundment, covering the west embankment interior slope (Photograph 36). Due to the presence of this fill material the interior slope could not be observed.

Erosion rills are present at the toe of the north embankment interior slope (Photograph 41).

The interior slope of the east embankment has been re-graded during summer of 2009 (Photograph 44).

2.3.4 Outlet Pipes

The outlet pipe in Ash Pond 2 appears to be in good condition. A 30-inch-diameter CMP discharges from the Ash Pond 2 precast concrete overflow structure directly into Ash Pond 2A. The invert elevation of the 30-inch-diameter outlet is approximately El. 695. The outlet appeared to be free of debris. No unusual movement was observed around the pipe penetration.

2.4 Ash Pond 2A

An overview of Ash Pond 2A photograph locations is shown on Figure 9c. Ash Pond 2A had areas of standing water and ash, with approximately 3.5 feet of freeboard. The pond's north, south, east, and west embankments serve as divider embankments between Ash Pond 1, Ash Pond 2B, Ash Pond 3 and Ash Pond 2, respectively. Pond 2A is charged by four (4) lines, consisting of two sump pit lines, the cinder pit, and the FGD hydroclone line (Photograph 46), located at the northwestern corner of the pond. Based on information provided by IPL, Ash Pond 2A was commissioned in 1992.

2.4.1 Exterior Slope

The exterior slopes appear to be in fair condition. Light vegetation covers the north embankment slope (divider embankment with Ash Pond 1) (Photographs 4 and 9). The north embankment exterior slope is approximately 3H:1V. There is no armoring present on the south embankment slope (divider embankment with Ash Pond 2B) and

much of the surface consists of exposed ash. The remaining exterior slopes have areas of vegetation from 12 to 36 inches in height, and trees with a maximum diameter of approximately 3 inches.

Erosion rills and several scarps were observed on the south embankment (divider embankment with Ash Pond 2B) (Photographs 72 and 73).

2.4.2 Crest

The crest appeared to be in fair condition (Photographs 51 and 61). In general, there are no signs of changes in the horizontal alignment. The crest serves as a vehicle access drive to the CCW impoundments. The average width of the embankment crest is 30 feet. A 5-foot-long section of the north embankment crest, in the vicinity of three 8-inch-diameter outfall pipes, has been eroded approximately 5 feet horizontally, resulting in a crest width of about 25 feet. This condition appears to infringe on the access drive (Photograph 46). Several minor depressions and areas of rutting were observed on the north embankment crest (Photograph 51).

2.4.3 Interior Slope

The interior slopes appear to be in fair condition. Erosion rills were observed along the north embankment. Erosion has undercut two active sluice lines in one location along the north embankment (Photographs 48 and 49). Riprap has been placed in several locations along the north embankment (Photograph 46), but in general the surface of the interior slopes defining Ash Pond 2A consists of exposed ash material, covered with light vegetation one to three feet in height (Photograph 55). Riprap on the north embankment near the waterline has been dislodged, apparently due to wave action (Photograph 54). Vegetation, consisting of brush and saplings, generally less than 30 inches in height, was observed on the interior slope of the north embankment (Photographs 52 and 54). The interior slopes generally appear to range from 2.5H:1V to 3H:1V. Scarps and beaching were observed on the east embankment where no armoring was present (Photographs 56 and 57). The embankment slope in these areas is approximately 1H:1V at the scarps (Photographs 56, 57 and 58).

The south embankment interior slope was armored with a layer of riprap to an elevation just above the water's surface (Photographs 50 and 61). Grass up to 18 inches high was observed along the waterline in this area (Photograph 60).

2.4.4 Outlet Pipes

The outlet pipes appear to be in fair condition. Ash Pond 2A discharges to Ash Pond 2B and Ash Pond 1 (when active). Both outlet pipes are 30-inch-diameter CMPs (Photographs 47 and 59). The outlet to Ash Pond 1 was about 90 percent obstructed by sediment.

2.5 Ash Pond 2B

An overview of Ash Pond 2B photograph locations is shown on Figure 9d. Ash Pond 2B contained standing water and ash at the time of this assessment and approximately 3.5 feet of freeboard. The pond's north, east and west embankments serve as divider embankments with Ash Ponds 2A and 3. Based on information provided by IPL, Ash, Pond 2B was commissioned in 1992.

2.5.1 Exterior Slope

The exterior slopes appeared to be in poor condition due to the presence of trees and brush. Trees up to 4 inches in diameter and light brush were observed on the exterior slope of the south embankment (Photograph 65). Sluice lines/pipes from the cinder pit, FGD hydroclone line and sump pump lines run along the north embankment (Photograph 69). Erosion was observed below pipes running along the east crest (Photograph 71). The south embankment slope was approximately 2H:1V.

2.5.2 Crest

The crest appeared to be in fair condition (Photographs 62 and 67). Minor areas of rutting were observed on the east and north embankment crest (Photograph 70). The average crest width of the east embankment (divider embankment with Ash Pond 3) is approximately 18 feet. The average crest width of the north, south and west embankment is approximately 30 feet. The crest surface appears to be compacted ash materials.

2.5.3 Interior Slope

The interior slopes appear to be generally in fair condition. Scarps were observed on a section of the west embankment (Photograph 63) and the eastern end of the north embankment interior slope (Photograph 73). The majority of the south embankment interior slope is armored with riprap (Photograph 62). The interior slopes generally appear to range from 2.5H:1V to 3H:1V, except in the areas of the observed scarps. In those areas, slopes appear to be approximately 1H:1V.

Vegetation, consisting primarily of brush less than 24 inches tall was observed on the interior slopes of the west, east and north embankments (Photographs 63 and 67).

2.5.4 Outlet Structure

The outlet structure between Ash Ponds 2B and 4A appeared to be in good condition (Photograph 66). This structure is controlled with a manually operated vertical slide gate. The inlet to Ash Pond 3 is located along the east embankment. This inlet was below the water surface and could not be observed (Photograph 68). Based on information provided by IPL, the connection between Pond 2B and Pond 3 was closed at the time of the assessment.

2.6 Ash Pond 3

An overview of Ash Pond 3 photograph locations is shown on Figure 9e. Ash Pond 3 contained standing water and ash at the time of this assessment. Ash Pond 3 had approximately 6 feet of freeboard. Based on information provided by IPL, Ash Pond 3 was commissioned in 1977.

2.6.1 Exterior Slope

The exterior slopes of Ash Pond 3 appear to be in fair condition. The west and south embankments serve as a divider embankment between Ash Pond 3 and Ash Ponds 2A, 2B and 4A. The HS Limestone Gypsum Conveyors have been installed on fill placed over the exterior slope of Ash Pond 3's east embankment. Heavy vegetation was present along the north embankment which obstructed view of the exterior slope (Photograph 14 is representative).

2.6.2 Crest

The crest appears to be in satisfactory condition (Photographs 84 and 90). The east, north and south embankment crests were widened in 1998 and surfaced with compacted gravel and crushed stone to accommodate truck traffic. The measured width of the east, north, and south embankment crests was approximately 40 feet. The surface of the west embankment crest appears to consist of compacted ash materials. The west embankment crest was measured to be approximately 20 feet wide.

2.6.3 Interior Slope

The interior slopes appear to be in poor condition. Much of the north embankment interior slope and a segment of the east embankment slope appeared to be armored with a layer of riprap, extending slightly below the water's surface (Photographs 86, 87 and 90). In general, the balance of the interior slopes is not armored. The interior slopes generally appear to range from 2.5H:1V to 3H:1V; except in areas of observed scarps. In those areas, slopes appear to be approximately 1H:1V.

Vegetation was observed on the north embankment (Photographs 80 and 85); the east embankment (Photographs 91, 94 and 95); the south embankment (Photograph 96); and the west embankment (Photographs 76, 81, and 101).

Surface erosion and localized sink holes were observed near the top of the west embankment interior slope (Photographs 81 and 82). Localized scarps were observed (up to 18 feet in length) on the west embankment (Photograph 77, 78, and 103). Vegetation, including brush and saplings with a maximum diameter of approximately 2 inches, lines the south embankment interior slope (Photograph 96 and 97).

A surficial slide, extending a distance of approximately 40-feet was observed on the east embankment near the mid-point of the embankment (Photos 92, 93 and 94). A sluice line (hydroclone) extends along the embankment crest, immediately adjacent to

and above the area of the slide (Photograph 94). It was observed that further encroachment into the crest may result in undermining of the sluice line. Some vegetation remains intact in vicinity of the east embankment where over-excavation of ash product (during harvesting) appeared to have infringed on the embankment interior slope (Photograph 91). Ash product, likely deposited by strong winds, was observed on the northwest corner of Ash Pond 3 (Photograph 80).

Riprap had been apparently placed in areas where erosion rills had formed in the past. However, some erosion rills were still visible near the top of the slope (Photographs 97 and 98). Erosion rills were observed along the interior slope resulting in a near-vertical slope along the east embankment (Photograph 97). Several rodent burrows were observed; one on the south embankment (Photograph 99) and one on the west embankment (Photograph 102).

2.6.4 Outlet Structure

The outlet structure appears to be in satisfactory condition. The outlets consist of three (3) 12-inch-diameter welded steel pipes that discharge into a drop outlet structure (Photograph 89). The submerged outlet appeared to be clear with no debris visible. Discharge from the drop outlet structure to Lick Creek is through an 18-inch-diameter reinforced concrete pipe (Photograph 88). Water was observed flowing into Lick Creek at the time of the site assessment.

2.7 Ash Pond 4

An overview of Ash Pond 4 photograph locations is shown on Figure 9f. Ash Pond 4 had standing water and ash at the time of the assessment, with approximately 4 feet of freeboard. Based on information provided by IPL personnel, Ash Pond 4 was formerly a gravel borrow pit that was commissioned 1983.

2.7.1 Exterior Slope

The exterior slopes appear to be in fair condition. The south and west embankments' exterior slopes were covered with trees (up to 18 inches in diameter) and heavy vegetation (Photographs 114, 121, and 124). The dense vegetation prohibited visual assessment. The south, east and west embankment slopes generally appear to be 3H:1V. The slope of the east embankment was covered with vegetation consisting of established grass, some shrubs, and small saplings (Photographs 128 and 129). The north embankment serves as a divider embankment for Ash Pond 4 and Ash Ponds 4A and 4B. The slope is generally not armored, and numerous areas of scarps, surficial slides, and surface erosion were observed. The slope was approximately 1H:1V.

2.7.2 Crest

The crest appears to be in good condition (Photographs 108, 115, 123, 130 and 135). The east, south and west embankment crests were widened in 1998 and surfaced with compacted gravel and crushed stone to accommodate vehicle traffic. The measured

width of the east, south and west embankment crests was approximately 40 feet. The surface of the north embankment appears to consist of compacted ash materials. The north embankment crest was measured to be approximately 20 feet wide. Tire ruts up to 6 inches deep were observed along the western embankment crest (Photograph 115).

2.7.3 Interior Slope

The interior slope of Ash Pond 4 appears to be in fair condition. The majority of the east embankment was armored with riprap (Photographs 131, 132, 133 and 134). Surface erosion was observed at the western end of the north embankment's interior slope (Photograph 109) and near the eastern end of the north embankment's interior slope (Photograph 137). There were a number of areas observed where riprap had been placed on the interior slope of the embankment in an apparent effort to address surface erosion (Photographs 122 and 135). At some of the locations where riprap had been placed, beaching was observed (Photographs 126 and 127). Vegetation including shrubs, saplings and grass, has grown to a height of about 2 feet on the north embankment (Photographs 105 and 109). Vegetation, generally less than 2 feet in height was present along the west embankment's interior slope (Photograph 117 and 120).

Ash sedimentation has reached the top of embankment along the south end of the west embankment interior slope (Photographs 117 and 118).

2.7.4 Outlet Pipes

The outlet pipes appear to be in good condition. The outlets discharge to Ash Pond 4B and consist of two 30-inch-diameter CMPs (Photograph 136). The CMP inlets and outlets appeared to be clear of sediment and debris.

2.8 Ash Pond 4A

An overview of Ash Pond 4A photograph locations is shown on Figure 9g. Ash Pond 4A had standing water and ash at the time of this assessment, with approximately 1.5 feet of freeboard. Based on information provided by IPL personnel, Ash Pond 4A was formerly a gravel borrow pit that was commissioned in 1983.

2.8.1 Exterior Slope

The exterior slopes of Ash Pond 4A appear to be in fair condition. The north, east and south embankments serve as divider embankments between Ash Pond 4A and Ash Pond 3, Ash Pond 4B and Ash Pond 4, respectively. These slopes are generally not armored. Slope erosion and slope failures were observed. The west embankment exterior slope was covered with trees up to 18 inches in diameter and heavy vegetation (Photograph 152). The heavy vegetation prohibited further visual assessment. The south, east and west embankment slopes generally appear to be 3H:1V.

2.8.2 Crest

The crest appears to be in fair condition. Tire ruts up to 6 inches deep were observed along the north and west embankments (Photographs 143, 147 and 148). Vegetation, consisting primarily of brush, generally less than 1 foot in height, covers the south embankment crest (Photograph 151). The measured width of the east, south and west embankment crests was approximately 40 feet. The surface of the north embankment appears to consist of compacted ash materials. The north embankment crest was approximately 20 feet wide.

2.8.3 Interior Slope

The interior slopes appear to be in poor condition. The north embankment interior slope is not armored. Erosion rills, beaching, and slope failures were observed around the entirety of the interior slope (Photographs 139, 140, 141, 144, 145, 146 and 153). The south embankment, which divides Ash Pond 4A and Pond 4 and serves vehicle traffic, has eroded into the crest by as much as 4 feet (Photograph 150). The interior slope was generally 1H:1V.

The east embankment interior slope has experienced beaching (Photograph 145).

The south embankment interior slope is generally very steep due to erosion.

The west embankment interior slope has eroded to approximately 1H:1V with some undercutting observed (Photograph 152).

2.8.4 Outlet Pipes

The outlet pipe to Ash Pond 4B consists of a 30-inch-diameter CMP and appears to be in poor condition. The pipe was apparently partly crushed in the past by construction equipment. The outlet pipe to Ash Pond 4B has been partly flattened which effectively reduces the cross-section of the pipe (Photograph 150). The outlet was partly submerged during the assessment and visibility was limited. It appeared that there was flow through the outlet. However, it could not be determined if sedimentation or debris was present at the pipe outlet (Photograph 149).

2.9 Ash Pond 4B

An overview of the Ash Pond 4B photograph locations is shown on Figure 9h. Ash Pond 4B had standing water and ash at the time of this assessment, with approximately 3 feet of freeboard. Based on information provided by IPL personnel, Ash Pond 4B was formerly a gravel borrow pit that was commissioned in 1983.

2.9.1 Exterior Slope

The exterior slopes of Pond 4B appear to be in fair condition. The north, west and south embankments separate Ash Pond 4B from Ash Pond 3, Ash Pond 4A and Ash Pond 4, respectively. These slopes are generally not armored. Slope erosion and surficial slides and scarps on the divider embankment with Ash Pond 3 were

observed. Saplings (approximately 1 to 2 inches in diameter) were observed along the exterior slope (Photograph 163). The south, east and west embankment slopes generally appear to be 3H:1V.

2.9.2 Crest

The crest appears to be in fair condition (Photographs 163, 168 and 170). Ruts were observed along the west embankment crest due to truck traffic (Photograph 170).

2.9.3 Interior Slope

The interior slopes are in fair condition. The north embankment interior slope was observed to have areas of undercutting (Photograph 155) and slope failures (Photograph 157). Vegetation on the north embankment interior slope consisted of brush, grass, and saplings, generally less than 36 inches in height (Photograph 156 and 157). The north embankment interior slope was observed to be approximately 1H:1V.

The east embankment interior slope was observed to have areas of undercutting and slides and scarps (Photograph 162). The southern end of the interior slope has been stabilized using riprap along approximately 40 percent of embankment (Photograph 162 and 164). The east embankment interior slope was approximately 1H:1V (Photograph 162).

The south embankment interior slope was approximately 1H:1V and was covered with vegetation including brush, grass and saplings. Vegetation was generally less than 30 inches in height (Photographs 164 and 167). Riprap has been used to stabilize some eroded areas (Photograph 166).

The west embankment interior slope was approximately 1H:1V and was covered with vegetation including brush, grass, and saplings. Vegetation was generally less than 30 inches in height (Photographs 158 and 170).

2.9.4 Outlet Pipes

The outlet pipes appear to be in fair condition. Water appeared to be flowing without obstruction through the 30-inch-diameter CMP (Photograph 154) that discharges into Ash Pond 3. A second 30-inch-diameter CMP discharge pipe, located on the west embankment, allows flow between Ash Pond 4A and Ash Pond 4B (Photograph 169).

2.10 Monitoring Instrumentation

Based on our review of the information provided to CDM, there is no monitoring instrumentation in place at the HS Generating Facility.

Section 3

Data Evaluation

3.1 Design Assumptions

CDM was not provided with any of the original IPL design assumptions for the CCW impoundments. IPL did provide some construction drawings related to the modifications and vertical expansion of Ash Pond 2 and Ash Pond 1.

3.2 Hydrologic and Hydraulic Design

CDM was not provided with any hydrologic and hydraulic designs and analyses for the impoundments.

CDM performed a preliminary evaluation of the hydraulic capacity of the impoundments to estimate if the ponds are adequately sized to store or pass the design storm event. Based on “General Guidelines for New Dams and Improvements to Existing Dams in Indiana”, IDNR (February 2010), the Probable Maximum Precipitation (PMP) for a 6-hour storm event over a 10 square-mile area in the vicinity of the site is approximately 27.3 inches. IDNR requires significant and high hazard structures to pass 50% PMP and 100% PMP, respectively. The drainage area contributing to the ponds at this site is limited to the storage area within the impoundments. Preliminary evaluations indicate that there is enough storage capacity and freeboard in Ponds 1, 2A, 2B, 4A and 4B at the current operating pools to safely store a 50% of the PMP event without being overtopped. Preliminary evaluation of Ponds 2, 3 and 4 indicates that there is enough storage capacity and freeboard at the current operating pool to safely store 100% of the PMP event without being overtopped.

3.3 Structural Adequacy and Stability

The IDNR requires new and existing structures to be evaluated under standard design guidelines. Procedures established by the United States Army Corps of Engineers (USACE), the United States Bureau of Reclamation, the Federal Energy Regulatory Commission, and the Natural Resources Conservation Service are generally accepted engineering practice. Minimum required factors of safety outlined by the USACE in EM 1110-2-1902, Table 3-1 and seismic factors of safety by FEMA Federal Guidelines for Dam Safety, Earthquake Analyses and Design of Dams (pgs. 31, 32 and 38, May 2005) are provided in [Table 3](#).

3.3.1 Ash Pond Impoundments

CDM was not provided with any information regarding the structural adequacy and stability of the HS Generating Station ash ponds. CDM was not able to perform stability analyses for the embankments because CDM was not provided with any information on the properties of the foundation and embankment soils.

Table 3 - Minimum Required Factors of Safety

Load Case	Minimum Required Factor of Safety
Steady-State Condition at Normal Pool or Maximum Storage Pool Elevation	1.5
Rapid Drawdown Condition from Normal Pool Elevation	1.2
Maximum Surge Pool (Flood) Condition	1.4
Seismic Condition at Normal Pool Elevation	1.0
Liquefaction	1.3

3.4 Foundation Conditions

CDM was not provided with sufficient information to evaluate if the ash pond impoundments were constructed on wet ash, slag, or other unsuitable materials. Section B-B, Typical Levee Section, shown on the IPL drawing titled "Pond 2 Levee Improvement Ash Pond Area Plan", dated 10/27/04, indicates that the embankment of Ash Pond 2 may have been constructed over hydraulically placed ash materials. Based upon the available information, it is not possible to completely evaluate the nature of the foundation material underlying the Ash Pond 2 embankment.

3.5 Operations and Maintenance

IPL personnel indicated that there is no written formal operation or maintenance program. They also do not have an emergency action plan. IPL personnel also indicated that there is no instrumentation in place to monitor water levels in the impoundments.

IPL HS Generating Station personnel were trained by BT SQUARED to perform visual inspections of the Ash Ponds. IPL personnel complete visual inspections of the impoundments every two weeks. A copy of the typical inspection checklist is provided in [Figure 10](#). As issues are observed, work orders are placed at the plant for the deficiencies to be repaired. Additional observations are made on a daily basis by IPL personnel familiar with the operation of the impoundments. These observations are not documented. Since 2008, semi-annual detailed visual inspections have also been performed by at the HS Generating Station by BTSQUARED. Inspection reports, with conclusions and recommendations, are prepared and submitted to IPL.

Section 4

Conclusions and Recommendations

4.1 Hazard Classification

The HS Generating Station impoundments currently do not have an IDNR-developed Hazard Potential Classification. Based on the USEPA classification system as presented on page 2 of the USEPA check list (**Appendix A**) and our review of the site and downstream areas, recommended hazard ratings have been assigned to the impoundments as summarized in **Table 4**.

4.2 Acknowledgement of CCW Impoundment Unit Condition

CDM acknowledges that the management units (Ash Ponds 1, 2, 2A, 2B, 3, 4, 4A, and 4B) referenced herein were assessed by William J. Friers, P.E. and Kyle R. King. Ash Ponds 1, 2, 2A, 2B, 3, 4, 4A, and 4B were judged to be in **FAIR** condition based on site observations. Observations at the time of the site assessment revealed eroded pond embankments and excessive vegetation. However, there is a lack of documentation relative to the design and construction of these facilities as identified in Section 3 of this report. It is not known if critical studies or investigations (stability, hydrologic, hydraulic, seismic) have been performed to confirm that potential safety deficiencies do not exist. Therefore, despite the **FAIR** condition assessment based on field observations, Ponds 1, 2, 2A, 2B, 3, 4, 4A, and 4B are judged to be in **POOR** condition based on lack of design documentation. An assessment of **POOR** for these ponds is due to lack of documentation relative to the design and construction of these facilities. Additional documentation and future studies performed to confirm the condition and performance of these impoundments and maintenance activities may be sufficient to substantiate an improved condition assessment.

As described in the following sections, further studies, maintenance, and monitoring could improve the condition of these impoundments.

4.3 Maintaining and Controlling Vegetation Growth

Dense vegetation obscured observation of the north embankment exterior slope of Ash Pond 1 and the west embankment exterior slope of Ash Pond 4. Vegetation including shrubs, brush and saplings, was prevalent on both internal and external embankment slopes of Ash Ponds 2B and 3 and the interior slopes of Ash Pond 2A. Typical practice is to remove 4-inch diameter and larger woody growth. Tree roots can allow for the seepage of the retained water through the embankments. This may lead to internal erosion of the embankment, resulting in a slope failure. In addition, uprooting of trees during storms or other adverse conditions can create large voids in the embankment that are then susceptible to erosion. Brush also obscures the surface, limiting visual observations, provides a haven for burrowing animals, and retards growth of desirable grass vegetation.

Table 4 – Recommended Impoundment Hazard Classification Ratings

Impoundment	Recommended Hazard Rating	Basis
Ash Pond 1	Significant Hazard	<ul style="list-style-type: none"> • A breach could have an environmental impact on Lick Creek and the White River. • A breach could damage/washout plant access and haul roads. • A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.
Ash Pond 2	High Hazard	<ul style="list-style-type: none"> • Ash Pond 2 has a total potential storage capacity of approximately 505 Acre-feet, with two feet of freeboard. • Considering that Ash Pond 2 may be utilized to store ash slurry in the future, a breach of south embankment could adversely affect adjacent stone quarry operations, and possibly result in worker's loss of life, due to the close proximity of the quarry to the south embankment. • A breach of the north embankment could have an environmental impact on Lick Creek and White River and possible property damage and loss of life downstream. • A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.
Ash Pond 2A	Low Hazard	<ul style="list-style-type: none"> • A breach could damage plant haul roads.
Ash Pond 2B	Low Hazard	<ul style="list-style-type: none"> • A breach could damage plant haul roads and slurry lines which discharge into Pond 2A.
Ash Pond 3	Significant Hazard	<ul style="list-style-type: none"> • Ash Pond 3 has a total potential storage capacity of approximately 100 Acre-feet. • A breach of the north embankment could have an environmental impact on Lick Creek and White River and cause possible property damage
Ash Pond 4	High Hazard	<ul style="list-style-type: none"> • Ash Pond 4 has a total storage capacity of approximately 300 Acre-feet, with two feet of freeboard. • A breach of south embankment could cause property damage at an adjacent stone quarry and possibly result in quarry worker's loss of life due to the close proximity of the quarry to Ash Pond 4. • A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.
Ash Pond 4A	Low Hazard	<ul style="list-style-type: none"> • A breach could impact haul roads and drainage ditches.
Ash Pond 4B	Low Hazard	<ul style="list-style-type: none"> • A breach could impact plant haul roads and drainage ditches.

CDM recommends that all trees and brush be cleared from the interior and exterior slopes of all ash pond embankments in accordance with the procedures outlined in “FEMA 534 Technical Manual for Dam Owners – Impacts of Plants on Earthen Dams”. CDM further recommends that stumps and all roots greater than 1 inch in diameter be removed. The area should then be graded to adjacent contours, using compacted structural fill and reseeded with desirable grass vegetation.

Areas of sparse vegetation observed on the exterior slope of Ash Pond 2. CDM recommends that IPL perform reseeding maintenance in these areas. CDM recommends that vegetation be cut on a regular basis to ensure that adequate visual observations can be made during scheduled inspections.

4.4 Erosion Protection and Repair

Erosion rills, beaching, surficial slope failures, and subsequent loss of grass cover were observed on multiple embankment slopes of all ash ponds as discussed in Section 2. CDM recommends corrective actions be taken for the specific conditions identified below:

- Deep erosion rills observed on the south embankment exterior slope of Ash Pond 2 and the north embankment exterior slope of Ash Pond 1:
 - IPL should repair by placing and compacting select structural fill in the rills and grading to adjacent contours. The area should be reseeded with desirable grass vegetation. Repairs made to erosion rills on slopes exceeding 25 feet in length should include installation of temporary erosion resistant matting or sod after regrading.
- Deep erosion rills the south embankment interior slope of Ash Pond 2 and erosion rills observed on slopes of divider embankments:
 - IPL should repair by placing and compacting select structural fill in the rills and grading to adjacent contours. Place rock riprap consisting of a heterogeneous mixture of irregular shaped rocks placed over the compact fill and a geotextile fabric, both extending at least 3 feet below the anticipated low water level. The maximum rock size and weight must be large enough to dissipate up the energy of the maximum anticipated wave action while holding the smaller stones in place.

IPL should note that caution will be required when working adjacent/below near vertical embankments created by surficial slides and scarps. Prior to start of work, the stability of the existing slope should be evaluated and a stabilization plan should be developed by a professional engineer as appropriate.

- Surficial slides and scarps on the south embankment interior slope of Ash Pond 2 and beaching and surficial slope failures observed on slopes of divider embankments:
 - IPL should repair by excavating the un-compacted eroded materials and organics (grass, brush, other vegetation) in the slide area to neat lines at the slide limits down to competent undisturbed materials. Restore the embankment face to a slope no steeper than 2.5H: 1V or the original contour (whichever is flatter) with compacted select structural fill. Place rock riprap consisting of a heterogeneous mixture of irregular shaped rocks placed over the compact fill and a geotextile fabric, both extending at least 3 feet below the anticipated low water level. The maximum rock size and weight must be large enough to dissipate the energy of the maximum anticipated wave action while holding the smaller stones in place.
- Excavated south embankment of Ash Pond 1 at cinder pit sluice repair:
 - Repair by removing un-compacted eroded materials to neat lines. Restore the embankment slope to a slope no steeper than 2.5H: 1V or the original contour (whichever is flatter) with compact select structural fill. Place rock riprap consisting of a heterogeneous mixture of irregular-shaped rocks placed over the compact fill and a geotextile fabric, both extending at least 3 feet below the anticipated low water level. The maximum rock size and weight must be large enough to break up the energy of the maximum anticipated wave action and hold the smaller stones in place.
- All repairs should be designed by a registered professional engineer experienced with earthen dam design.

4.5 Animal Control

Evidence of rodent burrows was observed on the west and south embankments of Ash Pond 3. Although not seen on other embankments, vegetation cover may have hidden additional rodent burrows. CDM recommends that IPL accurately document areas disturbed by animal activity, remove the animals, and repair the areas to protect the integrity of the embankments.

4.6 Instrumentation

Currently no information about existing instrumentation was available to CDM. An earth embankment that is safe under current conditions may not be safe in the future if conditions change. Conditions that may change include changes in the phreatic surface, embankment deformation, or changes in seepage patterns. CDM recommends installation of piezometers at selective locations so that parameters related to these conditions can be measured and preemptive measures can be taken in response to these observations.

4.7 Impoundment Hydraulic and Stability Analysis

IPL was not able to provide CDM with a hydraulic analysis showing the ability of the ash ponds to safely pass the 50% or 100% PMP event. However, a preliminary evaluation performed by CDM suggests there is enough storage capacity at the current operating pool levels to safely store precipitation from to 50% PMP. CDM recommends IPL perform a complete study to confirm this opinion and update the study if operating parameters of the ponds change in the information regarding stability analyses performed prior, during, or post construction for any ash ponds, nor information regarding properties of the embankment and foundation soils. It is recommended that detailed stability analyses be performed for all ash ponds.

The stability analyses for each pond should include a subsurface investigation program to determine the existing soil parameters in the embankments and foundation soils and the installation of piezometers to measure the phreatic surface.

CDM recommends IPL perform a study of the Ash Pond 2 embankment to determine the nature of the materials underlying the embankment and determine corrective measures required to address identified issues.

CDM was not provided with information regarding hydraulic analyses showing the ability of the Ash Pond Complex to safely pass the PMP event. It is recommended that detailed hydraulic analyses be performed to confirm the hydraulic stability of the Ash Pond Complex, and update the study if operating levels of the ponds change in the future or the embankment system is reclassified.

4.8 Inspection Recommendations

Based on the information reviewed by CDM it does not appear that IPL has adequate inspection practices. Currently inspection documentation prepared by plant personnel consist of limited checklists completed every two weeks for all five ponds to document the presence of any failures, erosion, vegetative cover in a “yes” or “no” format and to document operation conditions such as work activities. The inspection checklists are inadequate to document specific potential items that need to be addressed and the area where they are located. CDM recommends that plant personnel develop more-detailed inspection documentation procedures to aid in ensuring that they are performing adequate inspections and adequately documenting observations over time. Documentation should include a sketch of relevant features observed, and the documentation should be periodically reviewed to identify if conditions are worsening and/or if significant changes are occurring which could lead to additional maintenance issues or safety concerns.

A staff gage should be installed at outlet structures to record water levels in the impoundments, if applicable. In addition, inspections should be made following heavy rainfall and/or high water events on the White River, and the occurrence of

these events should be documented. It is recommended that inspection records be retained at the facility for a minimum of three years.

4.9 Emergency Action Plan

IPL does not have an Emergency Action Plan (EAP) for Ash Ponds 2 and 4, judged by CDM to be High Hazard structures. CDM recommends that IPL develop an EAP for Ash Ponds 2 and 4.

Section 5

Closing

The information presented in this report is based on visual field observations and review of reports and data provided to CDM by IPL for the Harding Street Generating Station surface impoundments. The conclusions and recommendations presented are based, in part, on limited information available at the time of this report. This report has been prepared in accordance with generally accepted engineering practices. No other warranty, expressed or implied, is made. Should additional information or changes in field conditions occur, the conclusions and recommendations provided in this report should be re-evaluated by a qualified professional engineer.

Section 6


Reports and References

The following is a list of reports and drawings that were provided by Indianapolis Power & Light Company and were utilized during the preparation of this report and the development of the conclusions and recommendations presented herein.

1. Response to U.S. EPA 104(e) Information Request, prepared by Indianapolis Power & Light Company, March 26, 2009
2. 2008 Dike Inspection – Harding Street Generating Station Ash Pond Facilities, prepared by BT SQUARED and Geosyntec Consultants, September 5, 2008
3. 2009 Dike Inspection-Harding Street Generating Station Ash Pond Facilities, BT² Project #3573, prepared by BT SQUARED, August 7, 2009
4. Section III, Technical Specifications, prepared by Indianapolis Power & Light Company, October 13, 2004 (date of email)
5. General Guidelines for New Dams and Improvements to Existing Dams in Indiana, prepared by the Department of Natural Resources, Division of Water, Indianapolis, Indiana, 2001 Edition
6. Log of Boring B-102 and corresponding Boring Location Plan, prepared by Patriot Engineering and Environmental, Inc., January 04, 2006 (date of boring)
7. Drawing No. Y-01, “Ash Disposal System Site Plan,” prepared by Burns and McDonnell, July 28, 1992
8. Drawing No. 006-00-6-Y-D-44AA “Harding Street Plot Plan,” prepared by Indianapolis Power & Light Company, July 22, 1991, revised January 9, 2009
9. Drawing No. 6-1-1-4-1, “Aerial Survey Topographic Map,” prepared by Indianapolis Power & Light Company, March, 1969
10. Drawing No. 6A6-156, “Property Plan,” prepared by Indianapolis Power & Light Company, September 26, 1968, revised April 5, 1980
11. Drawing No. C-1, “Pond 2 Levee Improvements Ash Pond Area Plan,” prepared by Indianapolis Power & Light Company, March, 2000
12. Drawing No. Unidentified, “Pond 2 Levee Improvements Ash Pond Area Plan,” prepared by Indianapolis Power & Light Company, October 27, 2004
13. Drawing No. 006-00-6-Y-D-42T, “Ash Pond Access Road Improvements,” prepared by Indianapolis Power & Light Company, September 15, 1997

14. Drawing No. 006-00-6-Y-D-42V, "Isolation Valve, Civil Details, Pond 2C," prepared by Indianapolis Power & Light Company, October 7, 1998
15. Drawing No. 006-00-6-Y-D-42M, "Ash Disposal System Site Plan," prepared by Indianapolis Power & Light Company, July 28, 1992
16. Drawing No. Y-01-C, "Ash Disposal System Site Plan," prepared by Indianapolis Power & Light Corporation, July 28, 1992
17. Drawing No. 006-00-6-Y-D-42P, "Ash Pond System Site Plan," prepared by Indianapolis Power & Light Company, March 20, 1996
18. Drawing No. 006-00-6-Y-D-42Q, "Ash Pond System Elevations and Details," prepared by Indianapolis Power & Light Company, March 20, 1996
19. Drawing No. 006-00-6-Y-F-42A, "Fly Ash Ponds Sheet #1, Stout Plant," prepared by Indianapolis Power & Light Company, July 3, 1974
20. Correspondence from Indianapolis Power & Light Company, August 19, 2010 to U.S. EPA Draft Report Comments.

Figures



USGS TOPOGRAPHIC MAPS
MAYWOOD QUADRANGLE MAP
CONTOURS AND ELEVATIONS IN FEET


CDM

consulting • engineering • construction • operations

INDIANAPOLIS, INDIANA
HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY

LOCUS PLAN
MAY 2010

FIGURE 1



AERIAL PHOTOGRAPH SOURCE:
GOOGLE EARTH PRO. (IMAGERY DATED MAY 10, 2010)



consulting • engineering • construction • operations

INDIANAPOLIS, INDIANA
HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY

CRITICAL INFRASTRUCTURE PLAN
MAY 2010
FIGURE 2




AERIAL PHOTOGRAPH SOURCE:
GOOGLE EARTH PRO. (IMAGERY DATED MAY 10, 2010)



consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

AERIAL MAP
FIGURE 3



NOTES:

1. SURVEY FROM INDIANAPOLIS POWER & LIGHT COMPANY "ASH POND SYSTEM SITE PLAN." MARCH 20, 1996
2. SURVEY WAS CONDUCTED BEFORE THE FINAL RAISING OF EMBANKMENTS ON ASH POND 2. SEE FIGURE 5.
3. PLANT DATUM IS -2.1' NGVD 29 DATUM.

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

1996 SURVEY MAP
FIGURE 4

1,000 0 2,000



CDM

consulting • engineering • construction • operations

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TLIFG005.dwg

NOTES:

1. FIGURE FROM INDIANAPOLIS POWER & LIGHT COMPANY
"POND 2 LEVEE IMPROVEMENTS ASH POND AREA PLAN."
OCTOBER 27, 2004
2. PLANT DATUM IS -2.1' NGVD 29 DATUM.



consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 2 FINAL LEVEE IMPROVEMENTS


FIGURE 5



PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TIRFG008a.dwg

NOTES:

1. FIGURE FROM PATRIOT ENGINEERING AND ENVIRONMENTAL, INC.
"BORING LOCATION PLAN, LIMESTONE/GYPSUM HANDLING AREA – IPL
HARDING STREET UNIT 7 FGD," JANUARY 04, 2006. FIGURE WAS NOT
PART OF A BOUND REPORT. HANDWRITTEN INFORMATION WAS
DRAFTED BY IPL PERSONNEL.





HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA


PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TIRFG008b.dwg

NOTES:

1. BORING LOG PROVIDED BY IPL PERSONNEL AND WAS NOT PART OF A BOUND REPORT. HANDWRITTEN INFORMATION WAS DRAFTED BY IPL PERSONNEL.



PW: \\CAMXSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009a.dwg





LEGEND:

② PHOTOGRAPH NUMBER AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991 (UPDATED JANUARY 9, 2009) DRAWING PREPARED BY INDIANAPOLIS POWER & LIGHT COMPANY




consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 1 PHOTOGRAPH LOCATION PLAN
FIGURE 9a

PW: \\CAMXSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009b.dwg




LEGEND:

② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY




consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 2 PHOTOGRAPH LOCATION PLAN

FIGURE 9b

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009c.dwg



LEGEND:

② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY

CDM


consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 2A PHOTOGRAPH LOCATION PLAN

FIGURE 9c

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009d.dwg



LEGEND:

② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY

50' 0 100'

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA


ASH POND 2B PHOTOGRAPH LOCATION PLAN

FIGURE 9d

CDM

consulting • engineering • construction • operations

PW: \\CAMXSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPLF009e.dwg




LEGEND:

② PHOTOGRAPH NUMBER AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991 (UPDATED JANUARY 9, 2009) DRAWING PREPARED BY INDIANAPOLIS POWER & LIGHT COMPANY



CDM


consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 3 PHOTOGRAPH LOCATION PLAN

FIGURE 9e

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009h.dwg



LEGEND:

② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY

CDM


consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 4 PHOTOGRAPH LOCATION PLAN

FIGURE 9f

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009f.dwg



LEGEND:

② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY

25' 0 50'


HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 4A PHOTOGRAPH LOCATION PLAN
FIGURE 9g

CDM

consulting • engineering • construction • operations

PW: \\CAMXMSVR01:PW_XM1\DOCUMENTS\51119\76658_HARDING_ST\03 REPORT AND STUDIES\09 CADD FIGURES AND GRAPHICS\TPFLG009g.dwg



LEGEND:

- ② PHOTOGRAPH NUMBER
AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 22, 1991
(UPDATED JANUARY 9, 2009) DRAWING
PREPARED BY INDIANAPOLIS POWER & LIGHT
COMPANY

50' 0 100'

CDM

consulting • engineering • construction • operations

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA

ASH POND 4B PHOTOGRAPH LOCATION PLAN
FIGURE 9h


ASH POND(S) INSPECTION RECORD HARDING STREET STATION

Date: 4/15/10 Time: 4:00pm

Ash Pond Description (Name/ID)	Erosion Along Crest or Embankment Slopes (Normal/Abnormal)	Appearance of Sinkholes or Failure (Y/N)	Tension Cracks Along Crest or Slope Faces (Y/N)	Presence of Vegetation Cover Along the Embankment Slopes (Y/N)	Changes in Dike Alignment (Y/N)	Appearance of Erosion/Deterioration Around Outlet Structures (Normal/Abnormal)	Description of Current Operational Conditions (Normal/Abnormal)	Initials Personnel
1	Normal	No	No	Yes	No	Normal	Normal Dry	TBD
2				no cap			I	TBD
2A							Normal wet	
2B								
3								
4								
4A								
4B								

This record is completed following twice monthly ash pond inspections

NOTES:



IPL INSPECTION CHECKLIST

Ash Pond Inspection Log 1_2009.doc

HARDING STREET GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
INDIANAPOLIS, INDIANA



consulting • engineering • construction • operations

TYPICAL BI-WEEKLY INSPECTION CHECKLIST
MAY 2010

FIGURE 10

Appendix A
USEPA Coal Combustion Dam
Inspection Checklist Forms



Site Name: IPL Harding Street Generating Station	Date: April 29, 2010
Unit Name: Ash Pond 1	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		683.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		n/a	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		see note 20
5. Lowest dam crest elevation (operator records)?		685.0	Is water exiting outlet, but not entering inlet?		see note 20
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?		see note 20
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)	X		At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.

2,6. No instrumentation is in place.

2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.

9. Vegetation overgrowth (small saplings, 1 to 2" diameter) along south embankment interior slope. Heavy vegetation and trees (up to 18" in diameter) located along north embankment exterior slope.

17,18,19. A 5' by 3' section of the south embankment was excavated to repair damage to a sluice line. Surface erosion along the northwest embankment interior slope. Surface erosion of the north embankment interior slope.

20. Pond is currently empty.

n/a = Not Available

d/n/a = Does Not Apply



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 1
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 1
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Fly ash and bottom ash processing.

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 11 Minutes 56.72 Seconds W
Latitude 39 Degrees 42 Minutes 29.49 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


X _____ **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

_____ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- 1) A breach could have an environmental impact on Lick Creek and the White River.
- 2) A breach could damage/washout plant access and haul roads.
- 3) A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.

CONFIGURATION:



- ☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 13 feet Embankment Material Earthen
 Pool Area 7 acres Liner None
 Current Freeboard d/n/a feet Liner Permeability d/n/a
 Pond is dry

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



 X **Outlet**

 1-30" inside diameter

Material


 X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)

 other (specify) _____



Is water flowing through the outlet? YES _____ NO X

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA



Site Name: IPL Harding Street Generating Station	Date: April 29, 2010
Unit Name: Ash Pond 2	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: <u>High</u> Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		692.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		706.0	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		n/a	Is water entering inlet, but not exiting outlet?		see note 20
5. Lowest dam crest elevation (operator records)?		720.0	Is water exiting outlet, but not entering inlet?		see note 20
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?		see note 20
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)	X		At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?	X		At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?	X		Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

<u>Inspection Issue #</u>	<u>Comments</u>
1.	Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
2,6.	No instrumentation is in place.
2,3,4,5.	Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.
9.	Trees (3" diameter) located at toe of south embankment exterior slope. Vegetation at toe of north embankment exterior slope.
10,11.	Ruts along crest from truck traffic.
17,18,19.	Small surface erosion area down south embankment exterior slope. Deep erosion rills along south embankment interior slope. Significant slough at toe of south embankment interior slope.
20.	Pond is currently empty.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 2
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 2
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Processing dredge spoils from Ponds 1 and 4.

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 12 Minutes 08.70 Seconds W
Latitude 39 Degrees 42 Minutes 23.96 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 X **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- 1) A breach of south embankment could adversely affect adjacent stone quarry operations, and possible result in worker's loss of life.
- 2) A breach of the north embankment could have an environmental impact on Lick Creek and White River and possible property damage and loss of life downstream.
- 3) A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.

CONFIGURATION:



- ☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 42 feet Embankment Material Earthen
 Pool Area 30 acres Liner None
 Current Freeboard d/n/a feet Liner Permeability d/n/a
 Pond is dry

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

☐ Trapezoidal

☐ Triangular

☐ Rectangular


☐ Irregular

☐ depth


☐ bottom (or average) width

☐ top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



☒ **Outlet** Outlet acts as overflow into Pond #2A, water leaves pond through evaporation

☐ 1-26" inside diameter

Material


☐ corrugated metal

☐ welded steel

☐ concrete

☒ plastic (hdpe, pvc, etc.)

☐ other (specify) _____



Is water flowing through the outlet? YES _____ NO ☒

☐ **No Outlet**

☐ **Other Type of Outlet** (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA



Site Name: IPL Harding Street Generating Station	Date: April 29, 2010
Unit Name: Ash Pond 2A	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		682.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		679.0	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		684.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X	At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.

2,6. No instrumentation is in place.

2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.

9. Shrubs and brush (small saplings, 1 to 2" in diameter) and erosion at northeastern embankment.

17,18,19. Surface erosion along north embankment interior slope (1'x10'). East embankment interior slope is approximately 1H:1V. Erosion runs below sluice pipes on north embankment.

n/a = Not Available
d/n/a = Does Not Apply



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # IN0004685
Date April 29, 2010

INSPECTOR Kyle King, Bill Friers

Impoundment Name Ash Pond 2A
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 2A
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

Is impoundment currently under construction?

Yes

No

X

Is water or ccw currently being pumped into the impoundment?

X

IMPOUNDMENT FUNCTION: Processing ash from hydroclone, cinder pit and sumps

Nearest Downstream Town : Name Indianapolis, Indiana

Distance from the impoundment 1.5 Miles

Impoundment

Location: Longitude 86 Degrees 11 Minutes 54.26 Seconds W

Latitude 39 Degrees 42 Minutes 25.79 Seconds N

State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 X **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 HIGH HAZARD POTENTIAL: Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A breach of Ash Pond 2A embankments could damage plant haul roads.

CONFIGURATION:



☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 12 feet Embankment Material Earthen
 Pool Area 3 acres Liner None
 Lowest Current Freeboard 3.5 feet Liner Permeability d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



 X **Outlet**

 2-30" inside diameter

Material


 X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)

 other (specify) _____



Is water flowing through the outlet? YES X NO

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA



Site Name: IPL Harding Street Generating Station	Date: April 29, 2010
Unit Name: Ash Pond 2B	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant <u>Low</u>
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		682.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		679.0	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		684.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)	X		At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.

2,6. No instrumentation is in place.

2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.

9. Vegetation (brush and small saplings, 1 to 2" in diameter) along the east embankment interior slope. Heavy vegetation/trees (4" in diameter) on south embankment exterior slope.

17,18,19. Erosion rills run under pipes along the east embankment crest. South embankment exterior slope is approximately 1H:1V. Erosion rills along the north embankment interior slope.

n/a = Not Available
d/n/a = Does Not Apply



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 2B
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 2B
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	<u>X</u>	_____

IMPOUNDMENT FUNCTION: Secondary processing of fly ash and bottom ash.

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 11 Minutes 50.35 Seconds W
Latitude 39 Degrees 42 Minutes 23.94 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 X **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 HIGH HAZARD POTENTIAL: Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A breach of Ash Pond 2B embankments could damage plant haul roads and slurry lines that discharge into Ash Pond 2A.

CONFIGURATION:



☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 13 feet Embankment Material Earthen
 Pool Area 2 acres Liner None
 Lowest Current Freeboard 3.5 feet Liner Permeability d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



 X **Outlet**

2-30" inside diameter

Material

 X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)


 other (specify) _____

Is water flowing through the outlet? YES X NO _____

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA





Site Name: IPL Harding Street Generating Station	Date: April 29, 2010
Unit Name: Ash Pond 3	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: <u>High</u> Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		679.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		n/a	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		685.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X	At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.

2,6. No instrumentation is in place.

2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.

17,18,19. Erosion and slope failure (18' x 5') along west embankment interior slope leaving section of the slope undercut and very steep. Slough observed near north end of the west embankment interior slope. Rodent burrows were encountered in the south and west embankment interior slopes.

n/a = Not Available
d/n/a = Does Not Apply

**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 3
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 3
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Final processing, "Clean Water Pond." Discharges into Lick Creek.

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 11 Minutes 46.33 Seconds W
Latitude 39 Degrees 42 Minutes 26.87 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 X **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A breach of Ash Pond 3 embankments into Lick Creek and White River could cause possible property damage and loss of life downstream.

CONFIGURATION:



☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 13 feet Embankment Material Earthen
 Pool Area 9.5 acres Liner None
 Lowest Current Freeboard 6 feet Liner Permeability d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



 X **Outlet**

 3-12" inside diameter

Material

 corrugated metal

 X welded steel

 concrete

 plastic (hdpe, pvc, etc.)


 other (specify) _____

Is water flowing through the outlet? YES X NO _____

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA





Site Name: IPL Harding Street Generating Station	Date: April 30, 2010
Unit Name: Ash Pond 4	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: <u>High</u> Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?		X
2. Pool elevation (operator records)? max		680.0	19. Major erosion or slope deterioration?		X
3. Decant inlet elevation (operator records)?		see note 3	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		682.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)	X		At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?	X		At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
- 2,6. No instrumentation is in place.
3. Inlet below water surface, not visible.
- 2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.
9. Heavy vegetation (trees up to 18" in diameter) on slope of west embankment exterior slope.
10. Ruts along west embankment crest.
17. Surface scarps on north embankment interior slope.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004685
Date April 29, 2010

INSPECTOR Kyle King, Bill Friers

Impoundment Name Ash Pond 4
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 4
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

Is impoundment currently under construction?

Yes

No

X

Is water or ccw currently being pumped into the impoundment?

X

IMPOUNDMENT FUNCTION: Fly ash and bottom ash processing.

Nearest Downstream Town : Name Indianapolis, Indiana

Distance from the impoundment 1.5 Miles

Impoundment

Location: Longitude 86 Degrees 11 Minutes 40.07 Seconds W

Latitude 39 Degrees 42 Minutes 15.12 Seconds N

State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 X **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- 1) A breach of southern embankment could cause property damage at an adjacent stone quarry and worker loss of life.
- 2) A breach could cause failure of adjacent lower ponds with discharge into Lick Creek.

CONFIGURATION:



☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest	Embankment Height	12	feet	Embankment Material	Earthen
	Pool Area	21	acres	Liner	None
Lowest	Current Freeboard	4	feet	Liner Permeability	d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

☐ Trapezoidal

☐ Triangular

☐ Rectangular

☐ Irregular


☐ depth

☐ bottom (or average) width


☐ top width

☐


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



☒ **Outlet**

☐ 2-30" inside diameter

Material

☒ corrugated metal

☐ welded steel

☐ concrete

☐ plastic (hdpe, pvc, etc.)


☐ other (specify) _____

Is water flowing through the outlet? YES ☒ NO ☐

☐ **No Outlet**

☐ **Other Type of Outlet** (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA





Site Name: IPL Harding Street Generating Station	Date: April 30, 2010
Unit Name: Ash Pond 4A	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)? max		682.0	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		681.6	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		685.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X	At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?		d/n/a	From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?	X		24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.

2,6. No instrumentation is in place.

2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.

17,18,19. Erosion rills along north embankment interior slope. Erosion rills and scarp/slough along east embankment interior slope. Erosion rills at east end of south embankment interior slope.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 4A
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 4A
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Fly ash and bottom ash processing.

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 11 Minutes 43.97 Seconds W
Latitude 39 Degrees 42 Minutes 21.74 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 X **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 HIGH HAZARD POTENTIAL: Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A breach in Ash Pond 4A embankment could impact plant haul roads and drainage ditches.

CONFIGURATION:



- ☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 13 feet Embankment Material Earthen
 Pool Area 1 acres Liner None
 Lowest Current Freeboard 1.5 feet Liner Permeability d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



X **Outlet**

1-30"

1-24" inside diameter

Material

X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)

 other (specify) _____

Is water flowing through the outlet? YES X NO

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA



Site Name: IPL Harding Street Generating Station	Date: April 30, 2010
Unit Name: Ash Pond 4B	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant <u>Low</u>
Inspector's Name: Kyle King, Bill Friers	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	see note 1			18. Sloughing or bulging on slopes?	X		
2. Pool elevation (operator records)? max	682.0			19. Major erosion or slope deterioration?	X		
3. Decant inlet elevation (operator records)? approx	679.0			20. Decant Pipes:			
4. Open channel spillway elevation (operator records)?	d/n/a			Is water entering inlet, but not exiting outlet?			X
5. Lowest dam crest elevation (operator records)?	684.0			Is water exiting outlet, but not entering inlet?			X
6. If instrumentation is present, are readings recorded (operator records)?	d/n/a			Is water exiting outlet flowing clear?			X
7. Is the embankment currently under construction?		X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X		From underdrain?			X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X		At isolated points on embankment slopes?			X
10. Cracks or scarps on crest?	X			At natural hillside in the embankment area?			X
11. Is there significant settlement along the crest?		X		Over widespread areas?			X
12. Are decant trashracks clear and in place?	d/n/a			From downstream foundation area?			X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X		"Boils" beneath stream or ponded water?			X
14. Clogged spillways, groin or diversion ditches?		X		Around the outside of the decant pipe?			X
15. Are spillway or ditch linings deteriorated?		X		22. Surface movements in valley bottom or on hillside?			X
16. Are outlets of decant or underdrains blocked?		X		23. Water against downstream toe?			X
17. Cracks or scarps on slopes?	X			24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
- 2,6. No instrumentation is in place.
- 2,3,4,5. Elevations shown reference NGVD 29. IPL's Harding Street Plant Datum is 2.1 feet lower than NGVD 29.
10. Surface crack along south embankment crest.
- 17,18,19. Scarp/slough of interior slopes is prevalent on north, south, and west embankments. East embankment interior slope has been stabilized with riprap.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004685 INSPECTOR Kyle King, Bill Friers
Date April 29, 2010

Impoundment Name Ash Pond 4B
Impoundment Company Indiana Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Ash Pond 4B
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	_____	<u>X</u>
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Tertiary treatment process of fly ash and bottom ash

Nearest Downstream Town : Name Indianapolis, Indiana
Distance from the impoundment 1.5 Miles
Impoundment
Location: Longitude 86 Degrees 11 Minutes 37.65 Seconds W
Latitude 39 Degrees 42 Minutes 22.19 Seconds N
State Indiana County Marion

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 X **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 SIGNIFICANT HAZARD POTENTIAL: Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 HIGH HAZARD POTENTIAL: Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A breach of Ash Pond 4B embankment could impact plant haul roads and drainage ditches.

CONFIGURATION:



☐ Cross-Valley
☐ Side-Hill
☒ Diked
☐ Incised (form completion optional)
☐ Combination Incised/Diked

Lowest Embankment Height 12 feet Embankment Material Earthen
 Pool Area 5 acres Liner None
 Lowest Current Freeboard 3 feet Liner Permeability d/n/a

TYPE OF OUTLET (Mark all that apply)

d/n/a **Open Channel Spillway**

 Trapezoidal

 Triangular

 Rectangular


 Irregular

 depth


 bottom (or average) width

 top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



X **Outlet**

1-30"

1-24" inside diameter

Material


X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)

 other (specify) _____



Is water flowing through the outlet? YES X NO

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Trans-Ash Inc. USA

Appendix B

Photographs



1. Ash Pond 1 - South Embankment Crest, Looking East



2. Ash Pond 1 - Inlet from Ash Pond 2A (30-inch-diameter CMP), Located at South Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



3. Ash Pond 1 - South Embankment Interior Slope, Looking East



4. Ash Pond 1 - Vegetation on South Embankment Interior Slope,
Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



5. Ash Pond 1 - South Embankment Crest, Repaired 8 inch Diameter Sluice Line



6. Ash Pond 1 - Excavation of Basin Floor (Approximately 6 feet deep, 55 feet long, 30 feet wide)



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



7. Ash Pond 1 - Sluice Line Repair at South Embankment Interior Slope



8. Ash Pond 1 - East Embankment Crest, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



9. Ash Pond 1 - East Embankment Interior Slope, Looking South



10. Ash Pond 1 - East Embankment Crest with Four (4) 8-inch-Diameter Sluice Lines and Vegetation



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



11. Ash Pond 1 - Four (4) 8-inch-Diameter Slice Lines along East Embankment Crest, Looking South



12. Ash Pond 1 - North Embankment Crest, Looking West, Depression Visible in Distance



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



13. Ash Pond 1 - North Embankment Interior Slope, Looking West, Area of Beaching is Visible in Distance



14. Ash Pond 1 - Dense Vegetation along North Embankment Exterior Slope, View from Bridge Over Lick Creek



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



15. Ash Pond 1 - North Embankment Exterior Slope



16. Ash Pond 1 - Beaching and Surface Erosion at the top of the North Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



17. Ash Pond 1 - Erosion Rill West of the North Embankment



18. Ash Pond 1 - West Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



19. Ash Pond 1 - Scarified Surface of West Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



20. Ash Pond 2 - South Embankment Interior Slope, Looking West,
Sparse Vegetation and Erosion Rills are Visible



21. Ash Pond 2 - Outlet Structure on East Embankment Interior
Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



22. Ash Pond 2 - South Embankment Exterior Slope, Looking West



23. Ash Pond 2 - South Embankment Exterior Slope, Looking North, Vegetation Located at on Slope and Toe



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



24. Ash Pond 2 - Ruts along South Embankment Crest, Looking East



25. Ash Pond 2 - Erosion Rill on South Embankment Exterior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



26. Ash Pond 2 - Erosion Rills on South Embankment Interior Slope



27. Ash Pond 2 - Surface Erosion along South Embankment Exterior Slope (Approximately 8' Width, 4' Deep, 30' Long)



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



28. Ash Pond 2 - Riprap used to fill in Erosion Rills, South Embankment Exterior Slope, Looking West



29. Ash Pond 2 - Erosion Rills Adjacent to Riprap on South Embankment Exterior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



30. Ash Pond 2 - Ruts along South Embankment Crest



31. Ash Pond 2 - Filter Fabric under Riprap Layer. Filter Fabric is used when Erosion Rill Extended to Crest



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



32. Ash Pond 2 - Surface Erosion below Riprap along South Embankment Exterior Slope



33. Ash Pond 2 - Deep Erosion Rill on South Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN



34. Ash Pond 2 - Erosion Rills and Undercutting of South Embankment Interior Slope, Looking South from Basin Floor



35. Ash Pond 2 - Erosion Rills and Slides on South Embankment Interior Slope, Looking East from Basin Floor



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



36. Ash Pond 2 - Dredging Spoil, West Embankment Interior Slope,
Looking North



37. Ash Pond 2 - West Embankment Interior Slope, Looking North
(Slope is approximately 3H:1V)



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



38. Ash Pond 2 - Northwest Embankment Exterior Slope, Looking West



39. Ash Pond 2 - North Embankment Exterior Slope, Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



40. Ash Pond 2 - North Embankment Crest, Looking East,
Established Vegetation on Exterior Slope



41. Ash Pond 2 - North Embankment Interior Slope, Looking North
from Basin Floor



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



42. Ash Pond 2 - East Embankment Interior Slope, View from Basin Floor



43. Ash Pond 2 - East Embankment Interior Slope, View from Basin



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



44. Ash Pond 2 - East Embankment Interior Slope, Looking South



45. Ash Pond 2 - East Embankment Exterior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



46. Ash Pond 2A - North Embankment Interior Slope, Looking East,
Three (3) 8-inch-Diameter Outfall Pipes



47. Ash Pond 2A - North Embankment Interior Slope, Riprap above
30-inch-Diameter Outlet and Erosion Rill on the Right



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN



48. Ash Pond 2A - Erosion Rill along North Embankment Interior Slope, View from Pond (Approximately 1' Wide, 10' Long)



49. Ash Pond 2A - North Embankment Interior Slope, Erosion Rill Undercuts Active Sluice Lines



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



50. Ash Pond 2A - Vegetation along South Embankment Interior Slope, Looking South



51. Ash Pond 2A - North Embankment Crest, Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



52. Ash Pond 2A - North Embankment Interior Slope, Looking West



53. Ash Pond 2A - South Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



54. Ash Pond 2A - North Embankment Interior Slope, Looking East,
Riprap Erosion at Waterline



55. Ash Pond 2A - Vegetation and Erosion on North Embankment



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



56. Ash Pond 2A - East Embankment Interior Slope, Looking North,
Approximate 1H:1V Slope



57. Ash Pond 2A - East Embankment Interior Slope, Looking South,
Slide (Scarp)



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



58. Ash Pond 2A - Overview of Steep East Embankment Interior Slope, Looking North, Approximate 1H:1V Slope



59. Ash Pond 2A - Outlet into Ash Pond 2B along the South Embankment Interior Slope, 30-inch-Diameter CMP



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



60. Ash Pond 2A - South Embankment Interior Slope, Looking South



61. Ash Pond 2A - South Embankment Crest, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



62. Ash Pond 2B - South Embankment Crest and Interior Slope,
Looking East



63. Ash Pond 2B - West Embankment Interior Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



64. Ash Pond 2B - North Embankment Interior Slope, Looking North



65. Ash Pond 2B - Vegetation along South Embankment Exterior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



66. Ash Pond 2B - Outlet Structure at East End of South Embankment



67. Ash Pond 2B - East Embankment Interior Slope, Looking North, Vegetation and Steep Slopes



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



68. Ash Pond 2B - Valved Outlet Access from East Embankment



69. Ash Pond 2B - Sluice Lines (Hydroclone and Sump) along Crest and Interior Slope of East Embankment, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



70. Ash Pond 2B - East Embankment Crest, Looking North



71. Ash Pond 2B - Erosion below Sluice Line along the East Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



72. Ash Pond 2B - North Embankment Interior Slope, Looking West



73. Ash Pond 2B - Scarp on Northeastern Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



74. Ash Pond 2B - North Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



75. Ash Pond 3 - Inlet (3 Valves) Along West Embankment Interior Slope, Looking North



76. Ash Pond 3 - West Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



77. Ash Pond 3 - Scarp along West Embankment Interior Slope
(Approximately 18 feet Long by 5 feet in Height)



78. Ash Pond 3 - Scarp and Beaching along West Embankment
Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



79. Ash Pond 3 - Riprap used to Stabilize Slope along West Embankment Interior Slope



80. Ash Pond 3 - Fines in Northwestern Corner of Pond



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



81. Ash Pond 3 - Surface Erosion at top of West Embankment
Interior Slope



82. Ash Pond 3 - Sink Holes on the West Embankment Interior
Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN



83. Ash Pond 3 - Vegetation on West Embankment Interior Slope,
Looking West



84. Ash Pond 3 - North Embankment Crest, Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



85. Ash Pond 3 - North Embankment Interior Slope, Looking North
From Outlet Control Structure



86. Ash Pond 3 - North Embankment Interior Slope, View from
Outlet Control Structure



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



87. Ash Pond 3 - East Embankment Interior Slope, View from Outlet Control Structure



88. Ash Pond 3 - Discharge into Lick Creek, North of Ash Pond 3



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



89. Ash Pond 3 - Ash Pond 3 Drop Inlet Structure/Discharge to Lick Creek, Looking North



90. Ash Pond 3 - East Embankment Crest, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



91. Ash Pond 3 - Beaching Along East Embankment Interior Slope,
Looking South



92. Ash Pond 3 - East Embankment Interior Slope, Looking South,
Extensive Erosion and Steep Slopes



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



93. Ash Pond 3 - Erosion Rills on top of East Embankment Interior Slope



94. Ash Pond 3 - Slope Erosion along East Embankment Interior Slope so as the Distance between the top of Slope and Hydroclone pipe is Approximately 2 feet



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



95. Ash Pond 3 - Southeastern Embankment Interior Slope, Looking South, Vegetation



96. Ash Pond 3 - Inflow from Ash Pond 4A Located at Southeastern Corner of Pond



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



97. Ash Pond 3 - South Embankment Interior Slope, Looking East



98. Ash Pond 3 - Erosion Rill above and Adjacent to Riprap along South Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



99. Ash Pond 3 - Rodent Burrow located in South Embankment Interior Slope



100. Ash Pond 3 - South Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



101. Ash Pond 3 - West Embankment Interior Slope, Looking North,
Slope is Undercut



102. Ash Pond 3 - Rodent Burrows in West Embankment Interior
Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



103. Ash Pond 3 - Erosion Rills and Beaching on West Embankment
Interior Slope



104. Ash Pond 3 - West Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



105. Ash Pond 4 - North Embankment Interior Slope, Looking West



106. Ash Pond 4 - Gate Valve located on North Embankment Crest



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



107. Ash Pond 4 - Submerged Inlet from Ash Pond 4A



108. Ash Pond 4 - North Embankment Crest, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



109. Ash Pond 4 - Erosion along the Northwestern Embankment
Interior Slope



110. Ash Pond 4 - West Embankment Interior Slope, View from
Pond



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



111. Ash Pond 4 - Sluice Lines Located along West Embankment
Interior Slope, Looking South



112. Ash Pond 4 - West Embankment Interior Slope, Riprap under
Sluice Line to Address Undercut



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



113. Ash Pond 4 - Freeboard along North Embankment Interior Slope




114. Ash Pond 4 - West Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



115. Ash Pond 4 - West Embankment Crest, Looking South,
Showing Ruts along Crest



116. Ash Pond 4 - Discharge into Pond along West Embankment
Crest



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



117. Ash Pond 4 - West Embankment Interior Slope and Pipeline,
Looking North



118. Ash Pond 4 - West Embankment Interior Slope, Looking South,
Ash Sediment Near top of Crest



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



119. Ash Pond 4 - Riprap used to Repair Erosion at Western Embankment Interior Slope



120. Ash Pond 4 - Vegetation along West Embankment Interior Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



121. Ash Pond 4 - West Embankment Exterior Slope, Heavy Vegetation on Slope



122. Ash Pond 4 - West Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



123. Ash Pond 4 - South Embankment Crest and Interior Slope,
Looking East



124. Ash Pond 4 - South Embankment Exterior Slope, Looking
West, Heavy Vegetation Present



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



125. Ash Pond 4 - South Embankment Interior Slope, Looking West,
Riprap Placed to Waterline



126. Ash Pond 4 - Southeastern Embankment Interior Slope,
Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



127. Ash Pond 4 - East Embankment Interior Slope, Looking North



128. Ash Pond 4 - East Embankment Exterior Slope, Looking North,
Established Vegetation on Slope, Brush and Saplings at Base of Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



129. Ash Pond 4 - East Embankment Exterior Slope, Looking South



130. Ash Pond 4 - East Embankment Crest, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



131. Ash Pond 4 - East Embankment Interior Slope, Looking South



132. Ash Pond 4 - East Embankment Interior Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



133. Ash Pond 4 - East Embankment Interior Slope, Looking North,
Riprap lines the Interior Embankment



134. Ash Pond 4 - Northeastern Embankment Interior Slope,
Looking North, Riprap lines the Interior Embankment



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



135. Ash Pond 4 - North Embankment Interior Slope, Looking West,
Vegetation is Present



136. Ash Pond 4 - Two (2) 30-inch-Diameter CMP Outlets to Ash
Pond 4B



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



137. Ash Pond 4 - Erosion of Riprap along the North Embankment
Interior Slope, Looking West



138. Ash Pond 4 - North Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



139. Ash Pond 4A - North Embankment Interior Slope, Looking West



140. Ash Pond 4A - Erosion Rill on North Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



141. Ash Pond 4A - North Embankment Interior Slope, Looking Southwest from Pond



142. Ash Pond 4A - Erosion Rills on North Embankment Interior Slope, Looking Northeast from Pond



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



143. Ash Pond 4A - North Embankment Crest, Looking West



144. Ash Pond 4A - Erosion Rill on North Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



145. Ash Pond 4A - Beaching at Base of East Embankment Interior Slope, Looking North



146. Ash Pond 4A - Erosion Rills and Beaching along North Embankment Interior Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



147. Ash Pond 4A - East Embankment Crest, Looking South



148. Ash Pond 4A - South Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN



149. Ash Pond 4A - Inlet/Outlet to Ash Pond 4B at Southeastern
Corner of Pond, Damage to 30-inch-Diameter CMP Visible



150. Ash Pond 4A - Erosion along South Embankment Interior
Slope, Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



151. Ash Pond 4A - South Embankment Crest, Looking West



152. Ash Pond 4A - West Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



153. Ash Pond 4A - Erosion Rills at North Embankment Interior Slope, Looking North



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



154. Ash Pond 4B - Outlet to Ash Pond 3 Located at Northeastern Corner of Pond



155. Ash Pond 4B - Undercut North Embankment Interior Slope, Looking East



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



156. Ash Pond 4B - North Embankment Interior Slope, Looking West



157. Ash Pond 4B - North Embankment Interior Slope, Looking West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



158. Ash Pond 4B - West Embankment Interior Slope, Looking West, Erosion Visible



159. Ash Pond 4B - East Embankment Interior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



160. Ash Pond 4B - North Embankment Interior Slope, Looking North



161. Ash Pond 4B - Tee-Joint, Typical of Pond Outlets



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



162. Ash Pond 4B - East Embankment Interior Slope, Looking South



163. Ash Pond 4B - East Embankment Exterior Slope, Looking South



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



164. Ash Pond 4B - Riprap used to Stabilize Slope along East Embankment Interior Slope, Looking South



165. Ash Pond 4B - High Inlet from Ash Pond 4, Low Inlet is approximately 5 feet West, Both Inlets are 30-inch-Diameter CMP's



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



166. Ash Pond 4B - Riprap on South Embankment Interior Slope,
Looking East



167. Ash Pond 4B - South Embankment Interior Slope, Looking
West



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



168. Ash Pond 4B - South Embankment Crest, Looking West



169. Ash Pond 4B - Inlet/Outlet to Ash Pond 4A located along West Embankment Interior Slope



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010



170. Ash Pond 4B - West Embankment Crest, Looking North, Ruts from Vehicle Traffic Visible



INDIANAPOLIS POWER & LIGHT COMPANY
HARDING STREET GENERATING STATION
INDIANAPOLIS, IN

CDM Project No.: 1801.034.SIT.HRDNG

April 29 and 30, 2010

Appendix C

Photo GPS Locations

Appendix C

Photo GPS Locations

Site: IPL Harding Street Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983

Coordinate Units: Feet

Photo No.	Northing	Easting
1	1,625,316.43	3,201,393.48
2	1,625,382.87	3,201,431.52
3	1,625,370.41	3,201,470.81
4	1,625,371.97	3,201,606.98
5	1,625,385.60	3,201,642.70
6	1,625,422.43	3,201,777.64
7	1,625,389.84	3,201,886.87
8	1,625,389.87	3,201,949.51
9	1,625,504.52	3,201,915.73
10	1,625,512.65	3,201,924.19
11	1,625,517.13	3,201,922.61
12	1,625,708.96	3,201,932.05
13	1,625,861.16	3,201,481.11
14	1,625,888.28	3,201,214.90
15	1,625,995.15	3,201,251.00
16	1,626,109.24	3,201,387.94
17	1,625,845.37	3,201,059.46
18	1,625,795.21	3,201,101.03
19	1,625,472.57	3,201,270.25
20	1,624,939.71	3,201,285.43
21	1,624,939.71	3,201,285.43
22	1,624,865.80	3,201,292.32
23	1,624,834.43	3,200,996.37
24	1,624,860.27	3,200,917.61
25	1,624,846.83	3,200,870.56
26	1,624,888.17	3,200,837.64
27	1,624,785.38	3,200,590.74
28	1,624,789.99	3,200,559.13
29	1,624,812.54	3,200,506.01
30	1,624,834.42	3,200,421.18
31	1,624,755.99	3,200,399.23
32	1,624,747.91	3,200,312.43
33	1,624,892.15	3,200,222.96
34	1,624,940.65	3,200,191.31
35	1,624,930.18	3,200,113.34
36	1,624,804.90	3,199,874.74
37	1,624,819.20	3,199,495.63
38	1,625,044.80	3,199,634.09
39	1,625,188.54	3,199,733.10
40	1,625,284.78	3,200,060.16
41	1,625,269.36	3,200,538.21
42	1,625,290.63	3,200,576.42
43	1,625,290.63	3,200,576.42
44	1,625,692.97	3,200,855.51

Appendix C

Photo GPS Locations

Site: IPL Harding Street Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983

Coordinate Units: Feet

Photo No.	Northing	Easting
45	1,625,486.87	3,201,173.55
46	1,625,307.96	3,201,409.21
47	1,625,315.88	3,201,422.88
48	1,625,301.35	3,201,515.75
49	1,625,311.07	3,201,568.00
50	1,625,310.33	3,201,582.42
51	1,625,346.57	3,201,601.01
52	1,625,337.82	3,201,726.49
53	1,625,328.83	3,201,854.73
54	1,625,350.16	3,201,704.33
55	1,625,336.64	3,201,953.34
56	1,625,290.60	3,202,011.37
57	1,625,300.06	3,202,001.31
58	1,625,225.85	3,202,029.38
59	1,625,194.41	3,201,789.73
60	1,625,194.41	3,201,789.73
61	1,625,069.61	3,201,725.36
62	1,625,045.58	3,201,812.48
63	1,625,045.58	3,201,812.48
64	1,625,045.58	3,201,812.48
65	1,625,032.16	3,201,838.63
66	1,624,953.16	3,202,237.75
67	1,624,969.16	3,202,259.68
68	1,625,082.21	3,202,172.31
69	1,625,093.38	3,202,173.70
70	1,625,093.38	3,202,173.70
71	1,625,135.14	3,202,138.18
72	1,625,199.47	3,202,078.63
73	1,625,199.47	3,202,078.63
74	1,625,192.82	3,201,978.67
75	1,625,246.29	3,202,080.88
76	1,625,246.29	3,202,080.88
77	1,625,392.33	3,201,998.08
78	1,625,407.16	3,201,995.81
79	1,625,418.97	3,201,995.11
80	1,625,556.29	3,201,961.72
81	1,625,574.29	3,201,959.52
82	1,625,566.52	3,201,970.43
83	1,625,681.63	3,202,013.29
84	1,625,697.67	3,202,045.24
85	1,625,596.65	3,202,189.45
86	1,625,596.65	3,202,189.45
87	1,625,596.65	3,202,189.45
88	1,625,804.82	3,202,106.62

Appendix C

Photo GPS Locations

Site: IPL Harding Street Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983

Coordinate Units: Feet

Photo No.	Northing	Easting
89	1,625,753.65	3,202,106.65
90	1,625,691.62	3,202,563.96
91	1,625,580.43	3,202,578.83
92	1,625,464.86	3,202,604.21
93	1,625,464.86	3,202,604.21
94	1,625,367.49	3,202,633.94
95	1,625,263.87	3,202,673.77
96	1,625,179.38	3,202,738.75
97	1,625,024.65	3,202,529.72
98	1,624,961.65	3,202,391.03
99	1,624,947.85	3,202,351.67
100	1,624,995.00	3,202,321.20
101	1,625,019.68	3,202,299.56
102	1,625,039.69	3,202,247.61
103	1,625,194.33	3,202,116.55
104	1,625,269.53	3,202,062.94
105	1,624,749.23	3,202,610.35
106	1,624,752.61	3,202,541.05
107	1,624,752.61	3,202,541.05
108	1,624,749.18	3,202,513.13
109	1,624,732.71	3,202,441.43
110	1,624,732.71	3,202,441.43
111	1,624,712.31	3,202,396.31
112	1,624,676.99	3,202,417.88
113	1,624,676.99	3,202,417.88
114	1,624,510.36	3,202,373.49
115	1,624,506.68	3,202,380.55
116	1,624,263.04	3,202,403.09
117	1,624,222.28	3,202,409.75
118	1,624,029.01	3,202,421.58
119	1,623,839.34	3,202,476.13
120	1,623,761.28	3,202,449.04
121	1,623,849.67	3,202,318.37
122	1,623,688.01	3,202,521.89
123	1,623,688.01	3,202,521.89
124	1,623,691.50	3,202,823.70
125	1,623,693.15	3,203,066.10
126	1,623,702.91	3,203,143.15
127	1,623,843.18	3,203,292.21
128	1,623,863.50	3,203,327.99
129	1,623,863.50	3,203,327.99
130	1,623,864.01	3,203,305.18
131	1,624,019.72	3,203,283.70
132	1,624,019.72	3,203,283.70

Appendix C

Photo GPS Locations

Site: IPL Harding Street Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983

Coordinate Units: Feet

Photo No.	Northing	Easting
133	1,624,019.72	3,203,283.70
134	1,624,475.28	3,203,267.60
135	1,624,646.77	3,203,229.81
136	1,624,683.88	3,203,106.90
137	1,624,705.44	3,203,047.20
138	1,624,746.32	3,202,753.80
139	1,624,918.98	3,202,432.78
140	1,624,918.98	3,202,432.78
141	1,624,946.28	3,202,538.19
142	1,624,946.28	3,202,538.19
143	1,625,009.75	3,202,598.63
144	1,625,020.03	3,202,634.87
145	1,625,020.03	3,202,755.72
146	1,624,975.78	3,202,657.27
147	1,624,885.77	3,202,627.34
148	1,624,885.77	3,202,627.34
149	1,624,821.35	3,202,631.01
150	1,624,782.12	3,202,614.20
151	1,624,759.12	3,202,571.79
152	1,624,759.84	3,202,445.42
153	1,624,759.84	3,202,445.42
154	1,625,032.35	3,202,802.62
155	1,625,057.53	3,202,865.73
156	1,625,057.53	3,202,865.73
157	1,625,139.85	3,203,003.61
158	1,625,139.85	3,203,003.61
159	1,625,194.93	3,203,102.31
160	1,625,165.11	3,203,160.38
161	1,625,172.67	3,203,217.30
162	1,625,092.73	3,203,261.27
163	1,625,050.65	3,203,306.50
164	1,624,892.59	3,203,271.49
165	1,624,705.29	3,203,099.53
166	1,624,733.55	3,202,958.77
167	1,624,746.88	3,202,816.77
168	1,624,753.51	3,202,778.04
169	1,624,796.23	3,202,671.04
170	1,624,821.49	3,202,646.23